Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	14781	(wear and drag)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 11:16
L2	156	1 and ((periodic\$5 oscilat\$8 reciprocal\$6) near3 (drive motive motion movement force load stress strain)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:12
L3	9	2 and ((force load stress strain wear drag compression) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 13:21
L4	21169	((periodic\$5 cycl\$6 oscilat\$8 reciprocal\$6) near3 (drive motive motion movement force load stress strain)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:42
L5	1161	4 and ((force load stress strain wear drag compression) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 14:25
L6	778	5 and control\$5.clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 16:59
L7	229	6 and (wear life)	USPAT; EPO; JPO	OR	ON	2004/11/17 12:18
L8	127	7 and (plurality two array multipl\$6 many several).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 13:33
L9	2	8 and (seocnd two pair) near3 ((periodic\$5 cycl\$6 oscilat\$8 reciprocal\$6) near3 (drive motive motion movement force load stress strain)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 16:57
L10	399	compressive near3 ((force load stress strain wear drag ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 13:22

L11	0	10 and drag near3 ((force load stress strain wear drag ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 13:24
L12	1	10 and drag .clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 13:24
L13	25	8 and axis.clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 13:28
L14	30	6 and (("2" two second other another) near3 (axis)).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 14:38
L15	19	6 and ((wear life ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 14:27
L16	21	6 and ((wear life fatigue ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 14:30
L17	21	6 and ((wear life fatigue endurance ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 17:02
L18	2	17 and (("2" two second other another) near3 (axis)).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 14:38
L19	1788	4 and (plurality seocnd two pair) near3 (force load stress strain)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 16:58
L20	44	4 and (plurality seocnd two pair) near3 (force load stress strain) near4 terminal	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 17:00
L21	34	20 and (process\$5 cpu computer control\$5).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 17:03
L22	10902	(plurality seocnd two pair) near3 (force load stress strain) near4 (test\$5 evaluat\$5 determin\$5 measur\$5 detect\$5 monitor\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 17:16

L23	65	22 and ((wear life fatigue endurance ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 17:17
L24	40	23 and (process\$5 cpu computer control\$5).clm.	USPAT; EPO; JPO	OR	ON	2004/11/17 17:17
L25	2049	(plurality seocnd two pair) near3 (force load stress strain) near4 (test\$5 evaluat\$5 determin\$5 measur\$5 detect\$5 monitor\$5). clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 17:16
L26	970	25 and (process\$5 cpu computer control\$5).cim.	USPAT; EPO; JPO	OR	ON	2004/11/17 17:17
L27	48	26 and ((wear life fatigue endurance ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 ))	USPAT; EPO; JPO	OR	ON	2004/11/17 17:26
L28	3523	((wear life fatigue endurance ) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5 )).ti.	USPAT; EPO; JPO	OR	ON	2004/11/17 17:27
L29	6	28 and 25	USPAT; EPO; JPO	OR	ON	2004/11/17 17:27